



Product Correction

Urgent - Immediate Action Required

Date Issued

April 5, 2019

Product

Product	List Number (LN)	Serial Number	UDI
Alinity i Processing Module	03R65-01	All	N/A
TED (Thermo-Electric Device) Engine, Reagent cooler	A-30103732-01 A-30103732-02	All	
CABLE, POWER OUT, TED CNTRLER	A-35006203-01 A-35006203-02	All	

Explanation

This letter is to inform you of potential loose cable connections on the reagent cooler, which could result in temperature errors and eventual reagent cooler failure.

A loose cable connection has the potential to heat up and cause damage to the wire and connector. If this occurs, the operator may detect a burning smell. The cable connection to the reagent cooler is located within the processing module and is not intended to be accessed by the operator. Due to the very low flammability rating of the materials used, any heat damage would be localized to the connectors.

The cable connections on the reagent cooler have been redesigned to include more robust connectors.

Patient/Safety Impact

The failure of the cable connections on the reagent cooler could result in unexpected instrument down time potentially causing a delay in generating results.

The system operator may be injured (electrical shock or burn) if he/she were to touch or come in direct contact with the exposed wire when the failure mode occurs.

Necessary Actions

If you experience unexpected reagent supply temperature errors, detect a burning smell or visible smoke, power off your Alinity i System and contact your Abbott representative.

Your Abbott representative will contact you to schedule the replacement of the impacted parts on your system.

If you have forwarded the product listed above to other laboratories, please inform them of this Product Correction and provide to them a copy of this letter.

Please retain this letter for your laboratory records.

**Contact
Information**

If you or any of the health care providers you serve have any questions regarding this information, U.S. Customers please contact Customer Service at 1-877-4ABBOTT (available 24 hours a day, 7 days a week). Customers outside the U.S., please contact your local area Customer Service.

Adverse reactions or quality problems experienced with the use of this product may be reported to the FDA's MedWatch Adverse Event Reporting program either online (<http://www.fda.gov/MedWatch/report.htm>), by mail (<http://www.fda.gov/MedWatch/getforms.htm>), by phone (1-800-332-1088), or by fax (1-800-FDA-0178).

If you have experienced any patient or user injury associated with this Field Action, please immediately report the event to your local area Customer Service.
