



# Product Correction

Immediate Action Required

**Date Issued** October 27, 2016

**Product**

Product	List Number	Serial Numbers
ACCELERATOR a3600 IOM	06P33-01	ACP009 to ACP129

**Explanation**

Abbott Diagnostics has received the attached letter from Inpeco, the manufacturer of the ACCELERATOR a3600. You are receiving this letter because the products listed below may have been installed with a potentially nonconforming cable (power cord) that may overheat. The specific cables impacted connect the power distribution bus to the following modules:

Product	List Number
ACCELERATOR a3600 Storage and Retrieval Module (SRM) 9000	06P46-01
ACCELERATOR a3600 Storage and Retrieval Module (SRM) 15000	06P46-21
Centrifuge Module	06P37-01
i2000SR Interface Module	06P49-02

**Patient Impact**

Please refer to the attached letter from Inpeco for information regarding risk to operator safety. There is no impact to patient results. Previously generated results are not impacted.

**Necessary Actions**

Abbott will be replacing the potentially nonconforming cables over the next several months. As parts become available, your Abbott service team will be contacting you to schedule replacement of the cables.

Please retain this letter for your laboratory records.

**Contact Information**

We sincerely regret any inconvenience this may have caused your laboratory. If you or any of the health care providers you serve have any questions regarding this information, U.S. Customers please contact Customer Service at 1-877-4ABBOTT (available 24 hours a day, 7 days a week). Customers outside the U.S., please contact your local area Customer Service.